Wood Destroying Insect Report

Dear Jack & Jill Buyers,

I have enclosed the Wood Destroying Insect Report for 82 Nice Dr. Great Town, PA 19000, performed on 1/4/2023.

The inspection is a limited visual inspection of the property for evidence of wood-destroying insect infestation. The inspection is based upon a careful visual inspection of the readily accessible areas of the structure at the time of the inspection.

This is a limited visual inspection of the structure in readily accessible areas. The inspection includes probing and/or sounding of unobstructed and accessible areas to determine the presence of visual evidence of wood-destroying insect infestation. Wood-destroying insect infestation and damage may exist in concealed or inaccessible areas. This is not an inspection for structural damage caused by infestation. Future infestation is beyond the scope of this inspection, such as an appearance of a termite swarm, or old inactive infestation turning active.

No inspection was made in areas that required the breaking apart or into, dismantling, or moving of any object, including but not limited to dirt, debris, moldings, floor coverings, wall coverings, siding, drop ceilings, insulation, furniture, appliances, and/or personal possessions; nor were there areas inspected which were obstructed or inaccessible for physical access on the date of the inspection.

Thank you for the opportunity to be of service to you.

Sincerely,

Dan Keogh

SunLight Inspection Services Scheduling Office: 610-450-6056 Office@SunLightInspections.com www.SunLightInspections.com

Wood Destroying Insect Inspection Report Notice: Please read important consumer information on page 2.							
Section I. General Information				Company's Business Lic. No. Date of Inspection			
SunLight Inspection Services				BU14262		1/4/2023	
1000 Gandia Eane, i nocinivino, i A 10 1 00				Address of Prope	ddress of Property Inspected		
(610) 450-6056 Great T				Great Town, PA			
Inspector's Name, Signature & Certification, Registration, or Lic. No. Structure(s) Inspected							
Dan Keogh		703024	De	12/	House Pro	oer	
Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:							
A. No visible evidence of wood destroying insects was observed.							
XB. Visible evidence of wood destroying insects was observed as follows:							
1. Live insects (description and location):							
 X 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location): Termite Shelter Tubes: In the crawl space on the center beam and on the foundation and floor joists along the back wall. At the back right corner of the garage on the foundation. 3. Visible. damage from wood destroying insects was noted as follows(description and location): NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage,may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer 							
or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.							
	recommended:(Explain i	FBox B in Section II is checked) of:	1				
					The inspector may write out obstructions or use the following optional key:		
	of the structure(s) inspected	were obstructed or inaccessible:			ed ceilings	15. Standing water	
X Basement	5				spended ceiling	16. Dense vegetation	
Crawlspace					ed wall covering or covering	17. Exterior siding18. Window well covers	
X Main Level	1, 3, 4, 6, 9				ulation	19. Wood pile 20. Snow	
XAttic	5, 11	5 11			oinets or shelving red items	21. Unsafe conditions	
X Garage	4.2.5				nishings	22. Rigid foam board	
X Exterior					oliances o access or entry	23. Synthetic stucco24. Duct work, plumbing	
	17				mited access	and /or wiring	
Porch					o access beneath	25. Spray foam insulation	
Addition					uttered condition	26. Equipment	
Other							
Section V. Additional Comments and Attachments (these are an integral part of the report) Please read page 2.							
Attachments:							
the buyer all information, to their knowledge, regarding W.D.I. infestation, rec				ignature of Buyer The undersigned hereby acknowledges eceipt of a copy of both page 1 and page 2 of this report and enderstands the information reported.			
x			x	x			

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection: A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage which may exist as of the date of the inspection. For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms. This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites: Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.

For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.

- 3. Obstructions and Inaccessible Areas: No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- 5. Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.

More Information

PHOTOS

Photos



Center beam in Crawl space



Back wall of crawl space



Back wall of the crawl sapce



Back right corner of the garage